

1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

<u> Horizon – Improper & Proper Installation</u>

The Horizon is designed to be **retrofit**. Recessing is permitted *only* at the bottom. The following scenarios illustrate mistakes to avoid and solutions.

Contents

Scenario 1: Upper endcap modified and measurement too tall	2
Scenario 2: Upper track cut <i>too short</i> and not level <i>front-to-back</i>	
Scenario 3: Upper track <i>modified</i>	4
Scenario 4: Lower track too low, gap, dirt, and exposed to elements	5
Scenario 5: <i>Gap</i> between track and housing	6
Scenario 6: Components concealed with finish	7
Scenario 7: Tracks and track runners butt jointed	8
Scenario 8: Lower endcap spigot broken during installation	8
Scenario 9: <i>Poorly maintained</i> unit, track runner cut <i>too short</i>	9

"Warranties" and "Maintenance & Operation" cards are available near the bottom of each product page. Click "Learn more".



Wizard Screens offers a 5 year limited warranty on all components. Learn more

REQUEST A QUOTE

Before quoting, it is *your* responsibility to *first* understand proper measuring and installation methods of the products.



1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 1: Upper endcap modified and measurement too tall.



	DO NOT	DO
1.	Modify parts. Doing so voids warranty!	Install parts as intended per guide.
2.	Disregard the measuring guide by measuring too tall for under-header application.	Measure according to the measuring guide. -1/2" Under Header
		Tight Measure minus 1/2"



1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 2: Upper track cut too short and not level front-to-back.



	DO NOT	DO
3.	- Cut upper track too short Cut in a way that allows gaps.	 Cut upper track to proper length according to measuring guide. Cut the assembled track at once. Before cutting, ensure extrusions are against track cap, and runner against latch before cutting – no gap! If runner is cut too short, cut track runner cut-off to size and fill gap at receiver end. *Upper and lower tracks must be cut to the same measurement.
4.	- Improperly position the upper latch.	- Flush upper latch with end of track .
5.	- Affix upper track out of level front-to-back. The pullbar will not operate optimally.	- Affix upper track <i>level front-to-back</i> . Shim if necessary.



1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 3: Upper track modified.



	DO NOT	DO
6.	Orient screws <i>vertically</i> through upper track . Doing so voids	Orient screws <i>horizontally</i> through upper track , per install guide.
	warranty!	½" min.



1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 4: Lower track too low, gap, dirt, and exposed to elements.



	DO NOT	DO
7.	Establish lower track mount too low in relation to housing = poor zipper transition = binding pull-bar	Establish bottom of lower track mount <i>flush</i> with bottom of housing .
∞.	Permit a gap between track and housing endcap = poor zipper transition.	Push track fully against housing endcap. Use mallet or flat bar to assist. *Will not work if step 7 not followed!
9.	 Mount where exposed to the elements - very bad. *Only 18x14 charcoal permitted for exterior mounts. Allow dirt and debris to collect. 	 Mount where protected from elements. If exterior mounted under shelter, this would still require more frequent maintenance than interior mounts. Clean tracks, then lubricate track runners with dry silicone regularly during high-use seasons. Warranty is void if items 9 are not honoured!



1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 5: Gap between track and housing.



	DO NOT	DO
10.	Cut track too short.	Before cutting, ensure track is <i>fully against</i> track cap . Track Cap (receiver end)
11.	Permit a gap between track and housing endcap .	Before affixing upper track mount , push <i>fully against</i> housing .
12.	Cut track runner too short. Items 10-12 consequences: = zipper unzipping = mesh possibly ripping	Cut track runner to fit between latch and housing.




1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 6: Components partly concealed with finish.





13. Conceal components. NEVER do this! Units must be serviceable. = cannot access upper track screws and possibly upper housing screw = not removable Defer to the "Horizon Integrated System (100mm only)".




1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 7: Tracks and track runners butt jointed.



	DO NOT	DO
14.	Butt joint tracks and track	Cut and install tracks as <i>one piece</i> for each top
	runners. NEVER do this!	& bottom.

Scenario 8: Lower endcap spigot broken during installation.



	DO NOT	DO
15.	Break the lower housing	Use a lower track cut-off to ensure the lower
	endcap spigot. If this	track mount is <i>properly aligned</i> before installing
	happens, order a new lower	it.
	housing endcap! Do not	If desired, though not necessary, file paint off
	attempt installation further!	spigot to make installation easier.
	This can happen if attempting	
	to force lower track onto the	
	spigot when lower track	
	mount is <i>improperly aligned</i> .	



1-888-949-3667

Wizard Screens

4263 Phillips Avenue Burnaby BC V5A 2X4

Scenario 9: Poorly maintained unit, track runner cut too short.



	DO NOT	DO
16.	Cut the track runner too short,	Cut the track runner to proper size.
	lest there be a gap.	
17.	 Forget to give the customer a warranty and maintenance card. Mount where exposed to the elements – very bad. 	Give the customer a warranty and maintenance card (see first page to locate). Instruct homeowner: - "Clean as often as room is cleaned. More often if exterior mounted." - "Apply dry silicone along <i>only</i> track runners every 4-6 weeks during higher-use seasons."