

## **Limitations, Operation & Maintenance for Clear Vinyl**

**Please be advised that Clear Vinyl expands and contracts based on changing weather conditions, so please follow these steps to ensure many years of trouble-free use:**

- The screens are designed to be operated in temperatures warmer than 0 degrees Celsius.
  - If the temperature drops below 0 degrees Celsius, do not operate the screens and leave them rolled down.
- Keep the vinyl screens rolled up when not in use.
- Allow the screens to warm up inside at least 24 hours before installation.
- After installation, please leave the screens down for at least 48 hours to allow the screens to acclimate to their new environment.
  - The screens will also require time to warm up in cooler temperatures.
  - If the screens are used near a heat source, turn the heat on at least 1 hour before operating the screens.
- Clear vinyl on clear vinyl welding does not hold up well in temperatures colder than 0 degrees Celsius.
  - As such, we recommend using a 4" Weblon border material between each piece of clear vinyl.
- Ensure the tracks are kept clean and thoroughly lubricated with Wizard Dry Silicone Spray.

- Use a coated clear vinyl specific cleaning and moisturizing product (IMAR, 303) and a clean microfiber cloth on the clear vinyl.



- Use of cleaning, waxing, polishing, or any cleaning product not specifically made for coated clear vinyl can leave the vinyl looking dull or stained.
  - Do not use a water repelling products on the screens.
  - Do not handle vinyl with sunscreen on your hands.